

## Layer Links

The PRISM 3D 5.0 Layer Link Tool enables specific sections of the 3D laser model to be hyperlinked to an external resource, such as a web link, PDF file, CAD drawing, etc. This provides a single entry point for accessing critical project and plant information from an intuitive 3D image of plant assets. The visual context for linked information, such as equipment data sheets, operating procedures, maintenance history, training materials, vendor manuals and best practices, makes it more usable and accessible, and thus more likely to be used.

### Adding a Layer Link

To use the layer link tool, double right-click on the desired region of the 3D laser model and select 'Add Layer Link'. The Links Dialog will appear. Select the type of link you'd like to add, enter or browse for the file/location of the link and then click accept.




Figure 1: Adding a Layer Link to a 3D Laser Model Volume





Figure 2: Layer Links Dialog

The linked layer will be shown as blue in the 3D laser model.



**Figure 3: A Layer Link in a 3D Laser Model**

Clicking on the blue section will open the specified link.



**Figure 4: The opened link**

To remove a link, double right-click again and select 'Remove Layer Link'.



## Quantapoint Office and Customer Support Contact Information

### Quantapoint Global Headquarters

275 Curry Hollow Road, Suite M100  
Pittsburgh, PA 15236  
USA

Telephone: +1-412-653-0100 – Customer Support is accessible via option #3 at the main menu

Fax: +1-412-653-2940

Web: [www.quantapoint.com](http://www.quantapoint.com)

General E-mail: [info@quantapoint.com](mailto:info@quantapoint.com)

Customer Support: [customer.support@quantapoint.com](mailto:customer.support@quantapoint.com)

### Process and Power Primary Contact: John Rothermel

Telephone: +1-412-653-0100, x-206

E-mail: [jrothermel@quantapoint.com](mailto:jrothermel@quantapoint.com)

### Architectural Primary Contact: Rob Johnson

Telephone: +1-412-653-0100, x-236

E-mail: [rjohnson@quantapoint.com](mailto:rjohnson@quantapoint.com)

### Waste Water and Utilities Primary Contact: Jay Lamy

Telephone: +1-412-653-0100, x-218

E-mail: [jlamy@quantapoint.com](mailto:jlamy@quantapoint.com)

### Quantapoint Gulf Coast / Offshore

5535 Memorial, F-609  
Houston, Texas 77007

USA

Telephone: +1-713-861-0883

### Primary Contact: Robert Bourbeau

Cell: +1-832-563-8900

E-mail: [rbourbeau@quantapoint.com](mailto:rbourbeau@quantapoint.com)

### Quantapoint Midwest / Power

1531 London Court  
Naperville IL 60563

USA

Telephone: +1-630-778-0502

Fax: +1-270-912-4596

### Primary Contact: Eric Hale

Cell: +1-630-300-4813

E-mail: [ehale@quantapoint.com](mailto:ehale@quantapoint.com)